

**To Redesign the Existing
Freedom Center located at
Freedom Park**

**Request for Proposal:
Due November 5, 2025, 2:00 pm**



www.pvrpd.org • 805-482-1996

Jessica A. Puckett, CPRE
Administrative Analyst
Pleasant Valley Recreation
and Park District, Camarillo, CA
(805) 482-1996, ext. 303
jpuckett@pvrpd.org
www.pvrpd.org

Request for Proposals – Professional Design Services Freedom Center Re-Design

The Pleasant Valley Recreation and Park District desires to identify and select a qualified architectural / engineering firm with the experience and design creativity to provide services in the phases of pre-design and schematic design options of the future remodel and renovations of the Freedom Center recreational building located at 515 Eubanks Street, Camarillo CA, 93010. Construction phase to be funded in future fiscal years.

- Proposals Due Date/Time: **Wednesday, November 5, 2025, 2:00 p.m.**
- SOQs must be received on or before the date and time indicated to:

Pleasant Valley Recreation and Park District

Attn: **Jessica A. Puckett, CPRE**

1605 E. Burnley Street

Camarillo, CA 93010

(Indicate RFQ Number, Name of Your Firm, and Project Name on lower left corner of envelope)

- Contact Information:
Telephone: (805) 482-1996, ext. 303
Email: jpuckett@pvrpd.org

RFP SCHEDULE		
1.	Pre-submittal Meeting and Site Walk-Through	October 21, 2025, 9:00 a.m.
2.	Deadline for submittal for clarifications or questions regarding the RFP to jpuckett@pvrpd.org	October 24, 2025
3.	Modifications and/or answers to questions posted on the PVRPD website at https://www.pvrpd.org/request-for-proposals-bids	October 27, 2025
4.	Submittal Deadline	November 5, 2025, 2:00 p.m.
5.	Committee evaluates Statement of Qualifications (SOQ) & selects preferred Firm	Nov. 6-Dec. 5, 2025
6.	Committee negotiates agreement with firm	Dec. 8-12, 2025
7.	Board of Directors awards contract (regular meeting)	January 7, 2026

Request for Proposals – Professional Design Services Freedom Center Re-Design

Contents

- Introduction**..... 4
- Project Goal** 4
- Project Scope of Work**..... 5
- Submission Requirements** 6
- Firm Selection** 8
- Project Schedule** 10
- Attachments:** 10

Request for Proposals – Professional Design Services

Freedom Center Re-Design

The Pleasant Valley Recreation and Park District (District) is soliciting proposals from qualified Architectural / Engineering Firms to provide architectural design services for the re-design and future remodel of the Freedom Center located within Freedom Park. The District seeks for the selected firm to analyze the existing conditions of the building in conjunction with the current and future recreational usage and needs of the community to provide a reimagined and renovated facility.

Introduction

The Pleasant Valley Recreation and Park District, an independent special district, was formed in January 1962 under the State Public Resources Code of California. The birth of the District was approved by the voters in the Camarillo community to provide quality programs, parks and facilities that could be enjoyed by everyone. The District is located in and around the city of Camarillo, serves a population of over 70,000 and covers an area of approximately 45 square miles. It has grown from one park to 28 parks since its inception 63 years ago. Within the District, a variety of recreational facilities exist including: a senior center, an indoor aquatic center, a community center, dog parks, lighted ball fields, tennis courts, a running track, walking paths, premier soccer fields, hiking trails, picnic pavilions, children’s play equipment, and barbecue areas.

The Freedom Center is an 8,973 sq. foot building located within Freedom Park. Freedom Park is home to the former Oxnard Air Force Base. The Base was first opened in 1940 and closed in 1945 and then reopened in 1951-1970. The Freedom Center served as the former Officers Club or Officers’ Open Mess for the base. The building features one large meeting hall with a raised stage, a side meeting room, full bar set-up in the back, a kitchen once used for a full commercial operation, eight storage rooms, an exterior built-in stage off the bar room, and two bathrooms (men’s and women’s). The Center was evaluated for ADA compliance as a part of the District’s 2022 ADA Transition Plan, and the findings are included in Attachment B.

Project Goal

The purpose of this project is two-fold; to evaluate the current recreational programming usage and future needs of the Freedom Center (Center) and based on that evaluation, provide the District with three tiers of potential design solutions for the renovation and/or remodeling of the facility to assist the District with determining the most appropriate long-term investment in the facility.

In order to attain this purpose, utilizing a public participation in the gathering of information, the contractor will generally need to, at minimum: identify the types of recreational activities currently performed in the Center; determine whether there is a surplus or shortage of indoor facility space available for the performance of these activities; quantify the amount of space needed to address any identified deficit, taking into account the likely time of day such activity can reasonably be expected to be performed by the affected population and provide reasonable estimates of the cost of expanded and/or new facilities to accommodate identified space needs.

Request for Proposals – Professional Design Services

Freedom Center Re-Design

Project Scope of Work

A key objective in this project is to stimulate public communication and facilitate community outreach in the completion of the following tasks:

Phase 1 – Evaluate Current Use of the Existing Freedom Center Facility

Objective: Document how the current Freedom Center Facility is used today and evaluate whether its current spaces can support potential alternative uses – all within the existing building footprint.

Tasks:

- Conduct an inventory of existing indoor spaces and assets (rooms, square footage, layout, current conditions, and specialized features such as flooring, mirrors, AV equipment, storage, etc.).
- The District will provide information on current indoor programming and private reservation usage by space (types of activities, frequency, participation levels, and scheduling patterns).
- Identify potential alternative uses that could occur within the existing footprint, based on current District goals, community demand, and in consultation with District staff and other related projects.
- Provide a brief comparative overview of how similar-sized facilities in nearby cities or agencies utilize their space (for context only).

Deliverables: a comprehensive report and electronic inventory documenting—

- Current indoor space allocation and use within the Freedom Center
- Gaps, overlaps, or underused areas
- Potential new or alternative uses that could fit within the existing footprint
- A brief comparative summary of other like-sized facilities

Phase 2 – Conceptual Redesign Alternatives

Objective: Translate the findings from Phase 1 into potential physical redesign solutions for the existing Freedom Center facility. This phase should focus on how the current building footprint could be renovated, reconfigured, or repurposed to meet identified community needs.

Tasks:

- Conduct a high-level building conditions assessment of the Freedom Center (structural, mechanical, electrical, plumbing, accessibility, and building code compliance, accessibility).
- Develop space planning diagrams showing how the existing footprint could be reorganized to support current and potential future uses.

Request for Proposals – Professional Design Services Freedom Center Re-Design

- Prepare three conceptual redesign alternatives (e.g., “Deluxe,” “Standard,” and “Economy”) that illustrate different levels of investment and scope of improvements. Assess capacity for modern technology integration.
- Provide schematic plans, diagrams, and illustrative renderings or sketches for each concept.
- Provide preliminary cost estimates for each alternative, including construction, soft costs, and contingencies (Rough Order of Magnitude).
- Identify any phasing strategies or operational impacts during construction.

Deliverables: a conceptual redesign package including—

- Space planning diagrams and schematic floor plans
- Visual renderings or conceptual sketches
- Preliminary cost estimates and comparison table
- Narrative descriptions of scope, benefits, and operational implications
- Phasing and implementation considerations for each alternative

Submission Requirements

The prospective Respondent shall submit ten (10) copies, plus an electronic version of the proposal to the Pleasant Valley Recreation and Park District. The proposals shall be signed by an authorized official of the firm. The District reserves the right to reject all proposals. They will not be opened publicly.

All acceptable proposals submitted must include the following:

Letter to the Selection Committee

This is your opportunity to introduce your team to us. What are the strengths of the entity that you wish the Selection Committee to take note of in the submittal? Other introductory material may be included. Firm advertising, brochures, and other promotional material should not be included.

Design Information

A statement of overall approach to the professional services required and why your firm may be best able to perform the work required. A statement on how you would coordinate the workload with your consulting firm, and if necessary, any sub-consultant(s). Proof of valid State Architect’s license must be submitted.

Technical Qualifications and Experience

The District desires a team who ideally brings the following experience:

1. Working together as a team on past projects
2. Design efforts which integrate a new facility into an existing architectural campus
3. Past design of public use facilities

Request for Proposals – Professional Design Services

Freedom Center Re-Design

4. Past design or expert consultation on public recreation centers
5. Past design for buildings of similar size, scope or complexity to this Project
6. Public engagement on capital projects

In addition to providing technical qualifications and experience, the Respondent is requested to provide detailed information on up to three projects completed within the past 8 years that you feel best illustrate your team’s qualifications to perform the Work. Please provide the Selection Committee with a brief description of these selected projects and photographs of the completed effort. The brief description should include when the project began, its current status, a description of the Respondent’s role/involvement in the project, and any specific information on how the design was responsive to the public. Please provide a hyperlink or hardcopy of similar projects completed by the firm.

Project Staffing and Organization

This section will be scored as to the qualifications of staff assigned to the Project. This submission shall include the key staff of the contracting firm and partner firms (if applicable). Information of use to the committee includes the length of time practicing in the profession, familiarity with design of public facilities and/or recreation centers.

1. Identify the project principal/officer who would be in charge, any discipline leads, and other subcontractors who you might expect to utilize in completing the Project.
2. Demonstrate the proposed design Project Manager’s individual experience within the past 15 years.
3. The cost estimation is a critical component of this project; therefore, we are requiring an independent cost estimator as a sub-consultant. Identify the experience of the construction cost estimator and other key personnel.
4. Provide a resume of any key specialty sub consultants.
5. The District must approve changes to key personnel committed to work on the project subsequent to award of contract.
6. A client reference list from previous projects of similar scope and magnitude. List should include key personnel, contact information and their position within the agency.

Project Understanding and Approach

This section should demonstrate the Respondent’s understanding of the project, how the work will be organized and anticipated key issues to be addressed. This section should:

1. Describe the overall approach to the Project, such as an outline work plan that describes how the Respondent will organize the Project. This section should generally summarize how the Respondent will address the items listed in the Scope of Work, while following up more specifically within further sections of the response.
2. Describe the opportunities you see for interfacing with the Community and Public Officials to:

Request for Proposals – Professional Design Services

Freedom Center Re-Design

- a. Verify types of programs
 - b. Review program details to include space and utilization
 - c. Set priorities, adjacencies, space sizes and locations
 - d. Inform the District and gather input from decision-makers
 - e. Stimulate public communication and facilitate community
 - f. Identify what you feel are the key components to making this project successful and where they will be addressed within the items listed in the Scope of Work.
3. Site Analysis
- a. Outline City, County, or State permitting process; EIR, CEQA, Code Compliance, etc.
 - b. Building Concepts
 - c. Building sketch concept options
 - i. Incorporating existing or adding onto the current building
 - ii. Incorporating Community input into specific building components
 - iii. Incorporating District Staff input into specific building components
 - iv. Phasing concept
 - v. Develop Schematic Designs
 - vi. Develop cost estimates

Financial and Other Information

The Respondent shall furnish the financial information requested below. If submitted by a consortium, a joint venture, a partnership, or by an individual, it shall be signed by an individual authorized to bind the firm making the proposal.

1. A firm must include in its proposal a complete disclosure of any alleged significant prior or ongoing contract failures, any civil or criminal litigation or investigation pending that involves the firm or in which the firm has been judged guilty or liable within the last five (5) years.
2. If there is no negative history to disclose, the firm must affirmatively state in its proposal that there is no negative history to report.
3. A detailed Scope of Work, including an itemization of all services to be provided and their individual costs. This should include estimated staffing, hours, cost, and a description of each major task and subtask, including public meetings.
4. A schedule of hourly rates to be charged for extra work if required during the course of the contract.
5. A disclosure of all personal, professional or financial relationships with any officer and/or employee of the District.

Firm Selection

The Request for Proposals invites Respondents to submit responsive materials describing their technical and management qualifications for the Project. The issuance of this RFP and the selection of the most qualified

Request for Proposals – Professional Design Services

Freedom Center Re-Design

firms is the first step in the design process that will eventually lead to the execution of an agreement with the most qualified firm.

Each proposal will be reviewed to determine if it meets the submittal requirements contained within this RFP. Failure to meet the requirements for the RFP can be cause for rejection of the proposal. The District will evaluate all proposals, and if your proposal is accepted the District may elect to set up interviews to help identify the most qualified firm. The proposals will be evaluated on a variety of factors including but not limited to:

Responsiveness to Submittal Requirements

Past Performance Record

Experience with work of similar complexity and scale. Efficiency and timeliness in completion of projects. Experience with projects completed for public entities.

Staffing Capabilities / Technical Competence

Familiarity with applicable codes and regulations. Training and proven expertise in the area of work required. Firms has available resources to complete work within expected time frame.

Approach to Work

Methodology to be implemented to address and coordinate the various elements within the project.

Quality Control

Demonstrated ability to provide professional level deliverables, accurate and qualified research and narrative writing style that meets professional and District standards.

Ease of Use

Final report shall contain enough technical detail to satisfy District staff, but also contain summaries and figures that will easily communicate its message to elected officials and the public.

Creativity

The District recognizes the complexity of this project and encourages the creativity in firms to accomplish the overall goal of this project.

References

The District will contact the references of the top proposals and will use that information in the evaluation and selection process.

Request for Proposals – Professional Design Services Freedom Center Re-Design

Fee

Fees charged in the proposal will be considered along with other proposal evaluation factors.

The successful Respondent to whom work is awarded shall, within 30 days of Board approval, enter into a contract with the District for the work in accordance with the specifications and shall furnish all required documents necessary to enter into said contract.

Failure to comply with the terms of these provisions may disqualify any proposal. Late submissions after the deadline will not be accepted. The District reserves the right to reject any proposal based upon the firm's prior documented history with the District or with any other party, which documents, without limitation, unsatisfactory performance, adversarial or contentious demeanor, significant failures to meet contract milestones or other contractual failures.

Project Schedule

1.	Board of Directors awards contract (regular meeting)	January 7, 2026
2.	Completion of a Preliminary Assessment	April 10, 2026
3.	Presentation of Final Report to District Board	July 1, 2026


Attachments:

Attachment A – Freedom Center Building Layout (1 page)

Attachment B – Freedom Center Report – 2022 ADA Transition Plan (52 pages)

Emergency Evacuation Plan

515 Eubanks - Freedom Center



 Fire Extinguisher

Emergency
Call 911

Selected Report Filters

The following report only includes records using the filter criteria options selected in DACTrak to generate this report. Not all non compliant records for this facility may have been included in this report. The complete report with most recent records is available in DACTrak.

The following filters have been applied to this report:

Location : Freedom Center

Categories : All Categories

Priorities : All

Assignments : All

Progress : All

Cost Responsibilities : All

Resolutions : All




Sort By : Priority

Report generated on: 9/15/2025 3:34:36 PM



Stairs

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17038</p> <p>Stairs to Multipurpose Room Stage</p> <p>Run 1</p> <p>The risers on the stairway are not a compliant height.</p> <p>Finding 8.00 inches</p> <p>Code 4.00 - 7.00 inches</p> <p>ADA 504.2, CA 11B-504.2</p>	<p>Modify or replace the stairs to provide compliant riser height.</p>	<p>Priority</p> <p>Not Set</p> <p>Resolution</p> <p>Not Set</p> <p>Progress</p> <p>Not Set</p> <p>Assignment</p> <p>Not Set</p>			<p>\$0.00</p>	
<p>Record Number 17037</p> <p>Stairs to Multipurpose Room Stage</p> <p>Run 1</p> <p>The treads do not have a compliant depth.</p> <p>Finding 9.00 inches</p> <p>Code At least 11.00 inches</p> <p>ADA 504, 504.2, CA 11B-504.2</p>	<p>Modify or replace the stairs to provide compliant treads.</p>	<p>Priority</p> <p>Not Set</p> <p>Resolution</p> <p>Not Set</p> <p>Progress</p> <p>Not Set</p> <p>Assignment</p> <p>Not Set</p>		<p>\$8,520</p>	<p>\$0.00</p>	
<p>Record Number 17039</p> <p>Stairs to Multipurpose Room Stage</p> <p>Run 1</p> <p>The height of the risers are not uniform.</p> <p>Finding Not Uniform</p> <p>ADA 504, CA 11B-504.2</p>	<p>Modify or replace the stairs to provide uniform riser height.</p>	<p>Priority</p> <p>Not Set</p> <p>Resolution</p> <p>Not Set</p> <p>Progress</p> <p>Not Set</p> <p>Assignment</p> <p>Not Set</p>		<p>\$8,520</p>	<p>\$0.00</p>	




Stairs

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17040</p> <p>Stairs to Multipurpose Room Stage</p> <p>Run 1</p> <p>There is no detectable striping on the stairways.</p> <p>Finding None Found</p> <p>ADA 504, CA 11B-504.4</p>	<p>Affix compliant contrasting striping to the upper approach and each tread that is the correct width and distance from the nosing.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,000</p>	<p>\$0.00</p>	
<p>Record Number 17036</p> <p>Stairs to Multipurpose Room Stage</p> <p>Run 1</p> <p>There are no handrails provided on the stairway.</p> <p>Finding None Found</p> <p>ADA 504, 505.2, 504.6, CA 11B-504.6, 505.2</p>	<p>Provide compliant handrails.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,528</p>	<p>\$0.00</p>	
<p>Record Number 17035</p> <p>Stairs to Multipurpose Room Stage</p> <p>Stairway is marked as primary access. There is no other means of vertical access.</p> <p>Finding No Access</p> <p>ADA 210, 504, 206.2, 402.2, CA 11B-206.2, 210, 402.2, 504</p>	<p>Provide a compliant means of vertical access.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$4,816</p>	<p>\$0.00</p>	




Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17069</p> <p>Freedom Center Front Office</p> <p>Push Side</p> <p>An unstable floor mat is provided at the door landing.</p> <p>ADA 403.2, 302.1, CA 11B-302.1,403.2</p>	<p>Provide a compliant floor mat for the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$126</p>	<p>\$0.00</p>	
<p>Record Number 17068</p> <p>Freedom Center Front Office</p> <p>Single Knob</p> <p>The door opening hardware is not accessible.</p> <p>Finding Not Accessible</p> <p>ADA 404.2, CA 11B-404.2</p>	<p>Provide accessible hardware on the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$800</p>	<p>\$0.00</p>	
<p>Record Number 17067</p> <p>Freedom Center Front Office</p> <p>The clear opening width of the door is less than required.</p> <p>Finding 29.25 inches</p> <p>Code At least 32.00 inches</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,750</p>	<p>\$0.00</p>	




Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16939</p> <p>Freedom Center Hallway Next to Mens Restroom Push / Pull</p> <p>The door opening force for this door is greater than allowed.</p> <p>Finding 8.00 pounds Code Up to 5.00 pounds ADA 404.2, CA 11B-404.2</p>	<p>Adjust the closer on the door to meet the door opening force requirements.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$25</p>	<p>\$0.00</p>	
<p>Record Number 16938</p> <p>Freedom Center Hallway Next to Mens Restroom</p> <p>The clear opening width of the door is less than required.</p> <p>Finding 28.00 inches Code At least 32.00 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,750</p>	<p>\$0.00</p>	
<p>Record Number 17028</p> <p>Freedom Center Kitchen Exterior Entrance</p> <p>The height of the threshold at the entrance door is greater than allowed.</p> <p>Finding 0.75 inches Code Up to 0.50 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Modify or replace the threshold to provide the recommended height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$436</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17027</p> <p>Freedom Center Kitchen Exterior Entrance</p> <p>Push Bar / D Handle</p> <p>The bottom of the door or gate does not provide a smooth surface on the push side extending the full width of the door or gate.</p> <p>Finding None Found</p> <p>ADA 404.2, CA 11B-404.2</p>	<p>Install a smooth uninterrupted surface or panel on the push side, extending the full width of the door or gate.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$400</p>	<p>\$0.00</p>	
<p>Record Number 17026</p> <p>Freedom Center Kitchen Exterior Entrance</p> <p>Push Bar / D Handle</p> <p>The door opening force for this door is greater than allowed.</p> <p>Finding 10.00 pounds</p> <p>Code Up to 5.00 pounds</p> <p>ADA 404.2, CA 11B-404.2</p>	<p>Adjust the closer on the door to meet the door opening force requirements.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$25</p>	<p>\$0.00</p>	
<p>Record Number 17188</p> <p>Freedom Center Kitchen Inner</p> <p>The clear opening width of the doorway is not compliant.</p> <p>Finding 31.00 inches</p> <p>Code At least 32.00 inches</p> <p>ADA 404, 404.2</p>	<p>Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,800</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17008</p> <p>Freedom Center Kitchen Outer</p> <p>Push / Pull</p> <p>The door opening force for this door is greater than allowed.</p> <p>Finding 6.00 pounds Code Up to 5.00 pounds ADA 404.2, CA 11B-404.2</p>	<p>Adjust the closer on the door to meet the door opening force requirements.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$25</p>	<p>\$0.00</p>	
<p>Record Number 17009</p> <p>Freedom Center Kitchen Outer</p> <p>Push / Pull</p> <p>Has a door stop.</p> <p>Finding Found ADA 404, 404.2, CA 11B-404.2</p>	<p>Remove the door stop.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$50</p>	<p>\$0.00</p>	
<p>Record Number 17007</p> <p>Freedom Center Kitchen Outer</p> <p>The clear opening width of the door is less than required.</p> <p>Finding 30.12 inches Code At least 32.00 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,750</p>	<p>\$0.00</p>	




Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16932</p> <p>Freedom Center Main Entrance</p> <p>The height of the threshold at the entrance door is greater than allowed.</p> <p>Finding 0.75 inches Code Up to 0.50 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Modify or replace the threshold to provide the recommended height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$436</p>	<p>\$0.00</p>	
<p>Record Number 16934</p> <p>Freedom Center Main Entrance</p> <p>Pull Side</p> <p>An unstable floor mat is provided at the door landing.</p> <p>ADA 403.2, 302.1, CA 11B-302.1,403.2</p>	<p>Provide a compliant floor mat for the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$126</p>	<p>\$0.00</p>	
<p>Record Number 16931</p> <p>Freedom Center Main Entrance</p> <p>Push Bar / D Handle</p> <p>The bottom of the door or gate does not provide a smooth surface on the push side extending the full width of the door or gate.</p> <p>Finding None Found</p> <p>ADA 404.2, CA 11B-404.2</p>	<p>Install a smooth uninterrupted surface or panel on the push side, extending the full width of the door or gate.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$400</p>	<p>\$0.00</p>	




Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16930</p> <p>Freedom Center Main Entrance</p> <p>Push Bar / D Handle</p> <p>The door opening force for this door is greater than allowed.</p> <p>Finding 10.00 pounds Code Up to 5.00 pounds ADA 404.2, CA 11B-404.2</p>	<p>Adjust the closer on the door to meet the door opening force requirements.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$25</p>	<p>\$0.00</p>	
<p>Record Number 16933</p> <p>Freedom Center Main Entrance</p> <p>Push Side</p> <p>An unstable floor mat is provided at the door landing.</p> <p>ADA 403.2, 302.1, CA 11B-302.1,403.2</p>	<p>Provide a compliant floor mat for the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$126</p>	<p>\$0.00</p>	
<p>Record Number 17244</p> <p>Freedom Center Mens Restroom Inner</p> <p>The clear opening width of the doorway is not compliant.</p> <p>Finding 28.75 inches Code At least 32.00 inches ADA 404, 404.2</p>	<p>Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,800</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16937</p> <p>Freedom Center Mens Restroom Outer</p> <p>Pull Side</p> <p>There is not enough clear floor space provided at the pull side of the door.</p> <p>Finding 37.50 inches</p> <p>Code At least 60.00 inches</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Provide the recommended clear floor space on the pull side of the door.</p>	<p>Priority</p> <p>Not Set</p> <p>Resolution</p> <p>Not Set</p> <p>Progress</p> <p>Not Set</p> <p>Assignment</p> <p>Not Set</p>		<p>\$2,921</p>	<p>\$0.00</p>	
<p>Record Number 16936</p> <p>Freedom Center Mens Restroom Outer</p> <p>Push / Pull</p> <p>Has a door stop.</p> <p>Finding Found</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Remove the door stop.</p>	<p>Priority</p> <p>Not Set</p> <p>Resolution</p> <p>Not Set</p> <p>Progress</p> <p>Not Set</p> <p>Assignment</p> <p>Not Set</p>		<p>\$50</p>	<p>\$0.00</p>	
<p>Record Number 16935</p> <p>Freedom Center Mens Restroom Outer</p> <p>The clear opening width of the door is less than required.</p> <p>Finding 27.50 inches</p> <p>Code At least 32.00 inches</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.</p>	<p>Priority</p> <p>Not Set</p> <p>Resolution</p> <p>Not Set</p> <p>Progress</p> <p>Not Set</p> <p>Assignment</p> <p>Not Set</p>		<p>\$1,750</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17075</p> <p>Freedom Center Multipurpose Room East Exterior Entrance</p> <p>The height of the threshold at the entrance door is greater than allowed for a vertical rise.</p> <p>Finding 0.50 inches</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Modify or replace the threshold to provide the recommended height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$257</p>	<p>\$0.00</p>	
<p>Record Number 17077</p> <p>Freedom Center Multipurpose Room East Exterior Entrance Pull Side</p> <p>An unstable floor mat is provided at the door landing.</p> <p>ADA 403.2, 302.1, CA 11B-302.1,403.2</p>	<p>Provide a compliant floor mat for the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$126</p>	<p>\$0.00</p>	
<p>Record Number 17073</p> <p>Freedom Center Multipurpose Room East Exterior Entrance Push Bar / Lever</p> <p>The bottom of the door or gate does not provide a smooth surface on the push side extending the full width of the door or gate.</p> <p>Finding None Found</p> <p>ADA 404.2, CA 11B-404.2</p>	<p>Install a smooth uninterrupted surface or panel on the push side, extending the full width of the door or gate.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$400</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17074</p> <p>Freedom Center Multipurpose Room East Exterior Entrance Push Bar / Lever</p> <p>Has a door stop.</p> <p>Finding Found</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Remove the door stop.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$50</p>	<p>\$0.00</p>	
<p>Record Number 17072</p> <p>Freedom Center Multipurpose Room East Exterior Entrance Push Bar / Lever</p> <p>The door opening force for this door is greater than allowed.</p> <p>Finding 12.00 pounds</p> <p>Code Up to 5.00 pounds</p> <p>ADA 404.2, CA 11B-404.2</p>	<p>Adjust the closer on the door to meet the door opening force requirements.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$25</p>	<p>\$0.00</p>	
<p>Record Number 17076</p> <p>Freedom Center Multipurpose Room East Exterior Entrance Push Side</p> <p>An unstable floor mat is provided at the door landing.</p> <p>ADA 403.2, 302.1, CA 11B-302.1,403.2</p>	<p>Provide a compliant floor mat for the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$126</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16922</p> <p>Freedom Center Multipurpose Room West Exterior Entrance Outer Pull Side</p> <p>There is not enough clear floor space provided at the pull side of the door.</p> <p>Finding 49.00 inches Code At least 60.00 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Provide the recommended clear floor space on the pull side of the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,921</p>	<p>\$0.00</p>	
<p>Record Number 16919</p> <p>Freedom Center Multipurpose Room West Exterior Entrance Outer Push Bar Only</p> <p>The door opening hardware is not accessible.</p> <p>Finding Not Accessible ADA 404.2, CA 11B-404.2</p>	<p>Provide accessible hardware on the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$800</p>	<p>\$0.00</p>	
<p>Record Number 16920</p> <p>Freedom Center Multipurpose Room West Exterior Entrance Outer Push Bar Only</p> <p>The door opening force for this door is greater than allowed.</p> <p>Finding 13.00 pounds Code Up to 5.00 pounds ADA 404.2, CA 11B-404.2</p>	<p>Adjust the closer on the door to meet the door opening force requirements.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$25</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16921</p> <p>Freedom Center Multipurpose Room West Exterior Entrance Outer Push Side</p> <p>There is less than the required latch side clearance on the push side of the door.</p> <p>Finding 11.00 inches Code At least 12.00 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Provide the recommended latch side clearance on the push side of the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,921</p>	<p>\$0.00</p>	
<p>Record Number 16915</p> <p>Freedom Center Northwest Bar Exterior Entrance</p> <p>The height of the threshold at the entrance door is greater than allowed.</p> <p>Finding 5.50 inches Code Up to 0.50 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Modify or replace the threshold to provide the recommended height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$436</p>	<p>\$0.00</p>	
<p>Record Number 16917</p> <p>Freedom Center Northwest Bar Exterior Entrance Pull Side</p> <p>An unstable floor mat is provided at the door landing.</p> <p>ADA 403.2, 302.1, CA 11B-302.1,403.2</p>	<p>Provide a compliant floor mat for the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$126</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16916</p> <p>Freedom Center Northwest Bar Exterior Entrance Pull Side</p> <p>There is no level landing at this door.</p> <p>Finding 3.10 percent Code Up to 2.08 percent ADA 302, 404, 305, 404.2, CA 11B-404.2</p>	<p>Provide a level landing.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,500</p>	<p>\$0.00</p>	
<p>Record Number 16913</p> <p>Freedom Center Northwest Bar Exterior Entrance Push Bar Only</p> <p>The door opening hardware is not accessible.</p> <p>Finding Not Accessible</p> <p>ADA 404.2, CA 11B-404.2</p>	<p>Provide accessible hardware on the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$800</p>	<p>\$0.00</p>	
<p>Record Number 16914</p> <p>Freedom Center Northwest Bar Exterior Entrance Push Bar Only</p> <p>Has a door stop.</p> <p>Finding Found</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Remove the door stop.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$50</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17232</p> <p>Freedom Center South Exterior Entrance</p> <p>The height of the threshold at the entrance door is greater than allowed.</p> <p>Finding 0.75 inches Code Up to 0.50 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Modify or replace the threshold to provide the recommended height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$436</p>	<p>\$0.00</p>	
<p>Record Number 17235</p> <p>Freedom Center South Exterior Entrance</p> <p>Pull Side</p> <p>An unstable floor mat is provided at the door landing.</p> <p>ADA 403.2, 302.1, CA 11B-302.1,403.2</p>	<p>Provide a compliant floor mat for the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$126</p>	<p>\$0.00</p>	
<p>Record Number 17234</p> <p>Freedom Center South Exterior Entrance</p> <p>Pull Side</p> <p>There is not enough clear floor space provided at the pull side of the door.</p> <p>Finding 55.75 inches Code At least 60.00 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Provide the recommended clear floor space on the pull side of the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,921</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17229</p> <p>Freedom Center South Exterior Entrance</p> <p>Push Bar Only</p> <p>The door opening hardware is not accessible.</p> <p>Finding Not Accessible</p> <p>ADA 404.2, CA 11B-404.2</p>	<p>Provide accessible hardware on the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$800</p>	<p>\$0.00</p>	
<p>Record Number 17230</p> <p>Freedom Center South Exterior Entrance</p> <p>Push Bar Only</p> <p>The bottom of the door or gate does not provide a smooth surface on the push side extending the full width of the door or gate.</p> <p>Finding None Found</p> <p>ADA 404.2, CA 11B-404.2</p>	<p>Install a smooth uninterrupted surface or panel on the push side, extending the full width of the door or gate.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$400</p>	<p>\$0.00</p>	
<p>Record Number 17231</p> <p>Freedom Center South Exterior Entrance</p> <p>Push Bar Only</p> <p>Has a door stop.</p> <p>Finding Found</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Remove the door stop.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$50</p>	<p>\$0.00</p>	




Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17233</p> <p>Freedom Center South Exterior Entrance</p> <p>Push Side</p> <p>An unstable floor mat is provided at the door landing.</p> <p>ADA 403.2, 302.1, CA 11B-302.1,403.2</p>	<p>Provide a compliant floor mat for the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$126</p>	<p>\$0.00</p>	
<p>Record Number 17125</p> <p>Freedom Center Southwest Bar Exterior Entrance</p> <p>The height of the threshold at the entrance door is greater than allowed.</p> <p>Finding 5.50 inches</p> <p>Code Up to 0.50 inches</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Modify or replace the threshold to provide the recommended height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$436</p>	<p>\$0.00</p>	
<p>Record Number 17126</p> <p>Freedom Center Southwest Bar Exterior Entrance</p> <p>Pull Side</p> <p>There is no level landing at this door.</p> <p>Finding 2.60 percent</p> <p>Code Up to 2.08 percent</p> <p>ADA 302, 404, 305, 404.2, CA 11B-404.2</p>	<p>Provide a level landing.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,500</p>	<p>\$0.00</p>	




Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17127</p> <p>Freedom Center Southwest Bar Exterior Entrance Pull Side</p> <p>An unstable floor mat is provided at the door landing.</p> <p>ADA 403.2, 302.1, CA 11B-302.1,403.2</p>	<p>Provide a compliant floor mat for the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$126</p>	<p>\$0.00</p>	
<p>Record Number 17123</p> <p>Freedom Center Southwest Bar Exterior Entrance Push Bar Only</p> <p>The door opening hardware is not accessible.</p> <p>Finding Not Accessible</p> <p>ADA 404.2, CA 11B-404.2</p>	<p>Provide accessible hardware on the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$800</p>	<p>\$0.00</p>	
<p>Record Number 17124</p> <p>Freedom Center Southwest Bar Exterior Entrance Push Bar Only</p> <p>Has a door stop.</p> <p>Finding Found</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Remove the door stop.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$50</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17066</p> <p>Freedom Center Womens Restroom Inner</p> <p>The clear opening width of the doorway is not compliant.</p> <p>Finding 28.87 inches Code At least 32.00 inches ADA 404, 404.2</p>	<p>Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,800</p>	<p>\$0.00</p>	
<p>Record Number 17228</p> <p>Freedom Center Womens Restroom Outer</p> <p>Pull Side</p> <p>There is not enough clear floor space provided at the pull side of the door.</p> <p>Finding 39.50 inches Code At least 60.00 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Provide the recommended clear floor space on the pull side of the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,921</p>	<p>\$0.00</p>	
<p>Record Number 17227</p> <p>Freedom Center Womens Restroom Outer</p> <p>Push / Pull</p> <p>Has a door stop.</p> <p>Finding Found</p> <p>ADA 404, 404.2, CA 11B-404.2</p>	<p>Remove the door stop.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$50</p>	<p>\$0.00</p>	

Doors

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17226</p> <p>Freedom Center Womens Restroom Outer</p> <p>Push / Pull</p> <p>The door opening force for this door is greater than allowed.</p> <p>Finding 9.00 pounds Code Up to 5.00 pounds ADA 404.2, CA 11B-404.2</p>	<p>Adjust the closer on the door to meet the door opening force requirements.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$25</p>	<p>\$0.00</p>	
<p>Record Number 17225</p> <p>Freedom Center Womens Restroom Outer</p> <p>The clear opening width of the door is less than required.</p> <p>Finding 27.50 inches Code At least 32.00 inches ADA 404, 404.2, CA 11B-404.2</p>	<p>Widen the door opening and install a door that provides at least the minimum clear width with the door open 90 degrees.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,750</p>	<p>\$0.00</p>	
<p>Record Number 17252</p> <p>Freedom Center Bar</p> <p>The height of the counter or desk does not comply with height requirements.</p> <p>Finding 43.37 inches Code 28.00 - 34.00 inches ADA 902, 904, CA 11B-904.4</p>	<p>Provide a portion of counter at the compliant height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$3,500</p>	<p>\$0.00</p>	

Signage

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17061</p> <p>Freedom Center Bar Entrance</p> <p>There is no compliant room identification signage provided.</p> <p>Finding None Found</p> <p>ADA 703, 216, 216.2, CA 11B-216.2</p>	<p>Install compliant room identification signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 17175</p> <p>Freedom Center Front Office</p> <p>There is no compliant room identification signage provided.</p> <p>Finding None Found</p> <p>ADA 703, 216, 216.2, CA 11B-216.2</p>	<p>Install compliant room identification signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 16961</p> <p>Freedom Center Hallway Next to Mens Restroom</p> <p>There is no compliant room identification signage provided.</p> <p>Finding None Found</p> <p>ADA 703, 216, 216.2, CA 11B-216.2</p>	<p>Install compliant room identification signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	

Signage

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17260</p> <p>Freedom Center Kitchen Exterior Entrance</p> <p>There is no room signage.</p> <p>Finding None Found</p> <p>ADA 216.2, 216.6, CA 11B-216.2,216.6</p>	<p>Install accessible room signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 16963</p> <p>Freedom Center Kitchen Inner</p> <p>There is no compliant room identification signage provided.</p> <p>Finding None Found</p> <p>ADA 703, 216, 216.2, CA 11B-216.2</p>	<p>Install compliant room identification signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 17223</p> <p>Freedom Center Kitchen Outer</p> <p>There is no compliant room identification signage provided.</p> <p>Finding None Found</p> <p>ADA 703, 216, 216.2, CA 11B-216.2</p>	<p>Install compliant room identification signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	

Signage

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17224</p> <p>Freedom Center Main Entrance</p> <p>There is no room signage.</p> <p>Finding None Found</p> <p>ADA 216.2, 216.6, CA 11B-216.2,216.6</p>	<p>Install accessible room signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 17245</p> <p>Freedom Center Multipurpose Room East Exterior Entrance</p> <p>There is no room signage.</p> <p>Finding None Found</p> <p>ADA 216.2, 216.6, CA 11B-216.2,216.6</p>	<p>Install accessible room signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 17095</p> <p>Freedom Center Multipurpose Room West Exterior Entrance Inner</p> <p>There is no room signage.</p> <p>Finding None Found</p> <p>ADA 216.2, 216.6, CA 11B-216.2,216.6</p>	<p>Install accessible room signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	




Signage

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17255</p> <p>Freedom Center Multipurpose Room West Exterior Entrance Outer</p> <p>There is no room signage.</p> <p>Finding None Found</p> <p>ADA 216.2, 216.6, CA 11B-216.2,216.6</p>	<p>Install accessible room signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 17165</p> <p>Freedom Center Northwest Bar Exterior Entrance</p> <p>There is no room signage.</p> <p>Finding None Found</p> <p>ADA 216.2, 216.6, CA 11B-216.2,216.6</p>	<p>Install accessible room signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 17043</p> <p>Freedom Center Office in Multipurpose Room</p> <p>There is no compliant room identification signage provided.</p> <p>Finding None Found</p> <p>ADA 703, 216, 216.2, CA 11B-216.2</p>	<p>Install compliant room identification signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	




Signage

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17033</p> <p>Freedom Center South Exterior Entrance</p> <p>There is no room signage.</p> <p>Finding None Found</p> <p>ADA 216.2, 216.6, CA 11B-216.2,216.6</p>	<p>Install accessible room signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 17063</p> <p>Freedom Center Southwest Bar Exterior Entrance</p> <p>There is no room signage.</p> <p>Finding None Found</p> <p>ADA 216.2, 216.6, CA 11B-216.2,216.6</p>	<p>Install accessible room signage.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 16955</p> <p>Freedom Center Mens Restroom</p> <p>The clear opening width of the doorway to the compartment is less than required.</p> <p>Finding 23.25 inches</p> <p>Code At least 32.00 inches</p> <p>ADA 404, 404.2, 604.8, CA 11B-604.8,404.2</p>	<p>Widen the doorway to provide a compliant clear opening width when the door is open 90 degrees.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$4,000</p>	<p>\$0.00</p>	



Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16957 Freedom Center Mens Restroom</p> <p>Door does not close automatically.</p> <p>Finding Missing Hardware</p> <p>ADA 404, 604.8, 604.8, CA 11B-604.8</p>	<p>Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be accessible.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$269</p>	<p>\$0.00</p>	
<p>Record Number 16954 Freedom Center Mens Restroom</p> <p>The door to the compartment does not have an accessible handle on both sides.</p> <p>Finding Not on both sides.</p> <p>ADA 404, 213, 604, 604.8, 604.8, CA 11B-404.2,604.8</p>	<p>Provide an accessible handle mounted on the door of the compartment near the latch.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$250</p>	<p>\$0.00</p>	
<p>Record Number 16958 Freedom Center Mens Restroom</p> <p>The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.</p> <p>Finding Not Accessible</p> <p>ADA 404, 404.2, 309.4, 604.8, CA 11B-404.2,604.8</p>	<p>Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$289</p>	<p>\$0.00</p>	




Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16956 Freedom Center Mens Restroom</p> <p>The compartment door is located in front of the water closet.</p> <p>Finding Not Located</p> <p>ADA 604.8, CA 11B-604.8</p>	<p>Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$4,000</p>	<p>\$0.00</p>	
<p>Record Number 16960 Freedom Center Mens Restroom</p> <p>There is less than the required latch side clearance on the pull side of the door.</p> <p>Finding 4.50 inches Code At least 18.00 inches</p> <p>ADA 404, 604.8, 604.8, 404.2, CA 11B-604.8,404</p>	<p>Provide required latch side clearance on the pull side of the door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,200</p>	<p>\$0.00</p>	
<p>Record Number 16959 Freedom Center Mens Restroom</p> <p>The inside handle is not located near the latch.</p> <p>Finding None Found</p> <p>ADA 404, 213, 604, 604.8, CA 11B-404.2,604.8</p>	<p>Adjust the inside handle so that it is located near the latch.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$129</p>	<p>\$0.00</p>	




Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16953 Freedom Center Mens Restroom</p> <p>There is less than the required minimum space in front of the toilet.</p> <p>Finding 30.25 inches Code At least 48.00 inches ADA 603, CA 11B-604.8</p>	<p>Create the required minimum clear space in front of the toilet.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$3,500</p>	<p>\$0.00</p>	
<p>Record Number 16948 Freedom Center Mens Restroom</p> <p>The distance from the center of the toilet to the nearest side wall does not meet the required distance.</p> <p>Finding 14.50 inches on center Code 17.00 - 18.00 inches ADA 603, 604.2, CA 11B-604.2</p>	<p>Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,500</p>	<p>\$0.00</p>	
<p>Record Number 16951 Freedom Center Mens Restroom</p> <p>The flush control on the toilet is not on the wide (approach) side of the toilet.</p> <p>Finding Wrong Side of Toilet ADA 603, 604.6, CA 11B-604.6</p>	<p>Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$127</p>	<p>\$0.00</p>	




Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16952 Freedom Center Mens Restroom</p> <p>The toilet does not provide the required distance from the center line to a fixture or wall on the wide side.</p> <p>Finding 16.00 inches Code At least 42.00 inches ADA 603, 604, CA 11B-604</p>	<p>Provide a compliant amount of clearance from the center line of the toilet to the nearest fixture or wall on the wide side.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$2,500	\$0.00	
<p>Record Number 16949 Freedom Center Mens Restroom</p> <p>The height of the toilet seat is not at the required height.</p> <p>Finding 16.50 inches Code 17.00 - 19.00 inches ADA 603, 604.4, CA 11B-604.4</p>	<p>Adjust or modify the toilet so the seat height is at the required accessible height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$1,707	\$0.00	
<p>Record Number 16941 Freedom Center Mens Restroom</p> <p>The location of the seat cover dispenser does not provide sufficient clear floor space.</p> <p>Finding Not Accessible</p> <p>ADA 304, 309.2, 305.1, CA 11B-603.5,309.2,305.1</p>	<p>Relocate the seat cover dispenser to a compliant height, that provides sufficient clear floor space, and does not interfere with use of the grab bars.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$277	\$0.00	




Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16947 Freedom Center Mens Restroom</p> <p>There are no grab bars.</p> <p>Finding None Found</p> <p>ADA 603, 609, 604.5, CA 11B-604.5</p>	<p>Install the required grab bars in the toilet compartment.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$267</p>	<p>\$0.00</p>	
<p>Record Number 16942 Freedom Center Mens Restroom</p> <p>There is no toilet paper dispenser provided on the narrow side wall.</p> <p>Finding None Found</p> <p>ADA 603, 604.7, CA 11B-604.7</p>	<p>Install a compliant toilet paper dispenser.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$277</p>	<p>\$0.00</p>	
<p>Record Number 16943 Freedom Center Mens Restroom</p> <p>The approach is to the latch side of the compartment door, clearance between the door side of the compartment and any obstruction does not meet the minimum required clearance.</p> <p>Finding 40.00 inches Code At least 42.00 inches</p> <p>ADA 603, 604.8, 404.2, CA 11B-604.8,404.2</p>	<p>Provide clearance between the door side of the compartment and any obstruction that meets the minimum required clearance.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$4,000</p>	<p>\$0.00</p>	




Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16944 Freedom Center Mens Restroom</p> <p>There is insufficient clear floor space in the compartment.</p> <p>Finding 30.50 inches Code At least 60.00 inches ADA 603, 213, 604, 604.8, CA 11B-604.8</p>	<p>Modify or replace the compartment to provide adequate clear floor space.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$4,000</p>	<p>\$0.00</p>	
<p>Record Number 16945 Freedom Center Mens Restroom</p> <p>There is insufficient clear floor space in the compartment.</p> <p>Finding 56.25 inches Code At least 59.00 inches ADA 603, 213, 604, 604.8, CA 11B-604.8</p>	<p>Modify or replace the compartment to provide adequate clear floor space.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$4,000</p>	<p>\$0.00</p>	
<p>Record Number 16946 Freedom Center Mens Restroom</p> <p>The height of the operable parts of the seat cover dispenser is greater than the allowed maximum height.</p> <p>Finding 56.00 inches Code Up to 40.00 inches ADA 309, 205, 308, 606, 308.2, CA 11B-603.5</p>	<p>Relocate the seat cover dispenser to a compliant height, that provides sufficient clear floor space, and does not interfere with use of the grab bars.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$277</p>	<p>\$0.00</p>	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17139 Freedom Center Mens Restroom Outer</p> <p>The height of the urinal rim in the restroom is not compliant.</p> <p>Finding 26.00 inches Code Up to 17.00 inches ADA 605, 605.2, CA 11B-605.2</p>	<p>Lower the urinal designated to be accessible in the restroom so that the rim height is compliant.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$1,397	\$0.00	
<p>Record Number 17140 Freedom Center Mens Restroom Outer</p> <p>The height of the urinal flush control in the restroom is greater than the required maximum height.</p> <p>Finding 53.00 inches Code Up to 44.00 inches ADA 605, 309.3, 605.4, 308.2, CA 11B-605.4</p>	<p>Lower the flush control valve on the urinal to a height not greater than the required maximum height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$227	\$0.00	
<p>Record Number 17141 Freedom Center Mens Restroom Outer</p> <p>The urinal does not meet the requirement for the minimum projection from the back wall to the front of the urinal rim.</p> <p>Finding 13.00 inches Code At least 13.50 inches ADA 605, 605.2, CA 11B-605.2</p>	<p>Install a urinal that meets the minimum projection requirements.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$951	\$0.00	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17142 Freedom Center Mens Restroom Outer</p> <p>There is less than the required clear floor space provided in front of the urinal in the restroom to allow an accessible forward approach.</p> <p>Finding 29.75 inches Code At least 30.00 inches ADA 605, 605.3, 305.3, CA 11B-605.3,305.3</p>	<p>Provide the required minimum clear floor space in front of the urinal designated to be accessible in the restroom, for a forward approach.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$1,707	\$0.00	
<p>Record Number 17138 Freedom Center Mens Restroom Outer</p> <p>The bottom edge of the reflective surface of the mirror is not at the correct height.</p> <p>Finding 46.50 inches Code Up to 40.00 inches ADA 603, 213, 603.3, CA 11B-603.3</p>	<p>Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$300	\$0.00	
<p>Record Number 17143 Freedom Center Mens Restroom Outer</p> <p>Door Sign - Male</p> <p>There is no gender use signage on the entrance door.</p> <p>Finding None Found CA 11B- 216.8,703.7</p>	<p>Post gender use signage on the center of the door at the required height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$158	\$0.00	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17133</p> <p>Freedom Center Mens Restroom Outer Lavatory</p> <p>The lavatory center line does not meet the minimum required distance when located adjacent to a side wall, partition or fixture.</p> <p>Finding 14.50 inches on center Code At least 18.00 inches on center CA 11B- 606.6</p>	<p>Replace or remount lavatory to meet the minimum required distance to the center line of the fixture, when located adjacent to a side wall or partition.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,500</p>	<p>\$0.00</p>	
<p>Record Number 17134</p> <p>Freedom Center Mens Restroom Outer Lavatory</p> <p>There is not sufficient clear floor space provided to allow an accessible forward approach.</p> <p>Finding 40.00 inches Code At least 48.00 inches ADA 213, 606, 606.2, 305.3, CA 11B-606.2, 305</p>	<p>Relocate the lavatory to provide clear floor space.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,261</p>	<p>\$0.00</p>	
<p>Record Number 17135</p> <p>Freedom Center Mens Restroom Outer Lavatory</p> <p>The pipes under the lavatory do not provide protection against contact.</p> <p>Finding Pipes not wrapped. ADA 213, 606, 606.5, CA 11B-606.5</p>	<p>Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$149</p>	<p>\$0.00</p>	



Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17131</p> <p>Freedom Center Mens Restroom Outer Lavatory</p> <p>The apron height under the lavatory is less than the required minimum height.</p> <p>Finding 27.37 inches Code At least 29.00 inches ADA 213, 606, 306.3, CA 11B-306.3,606.2</p>	<p>Raise or replace the lavatory to provide the minimum required apron height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$2,500	\$0.00	
<p>Record Number 17132</p> <p>Freedom Center Mens Restroom Outer Lavatory</p> <p>The knee clearance space under the lavatory is less than the required minimum height.</p> <p>Finding 24.75 inches Code At least 27.00 inches ADA 213, 606, 606.2, 306.3, CA 11B-606.2,306.3</p>	<p>Raise or replace the lavatory to provide the minimum required knee clearance.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$1,286	\$0.00	
<p>Record Number 17136</p> <p>Freedom Center Mens Restroom Outer Lavatory</p> <p>The supply lines under the lavatory do not provide protection against contact.</p> <p>Finding Not Wrapped ADA 213, 606, 606.5, CA 11B-606.5</p>	<p>Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$149	\$0.00	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17137</p> <p>Freedom Center Mens Restroom Outer Lavatory</p> <p>The metered water faucet remains open for less than the required amount of time.</p> <p>Finding 6.00 seconds Code At least 10.00 seconds ADA 606.4, CA 11B-606.4</p>	<p>Provide compliant metered faucet that remains open for a compliant amount of time.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>			<p>\$0.00</p>	
<p>Record Number 17130</p> <p>Freedom Center Mens Restroom Outer Paper Towel</p> <p>The height of the controls and operating mechanisms for the dispenser is not at the correct height.</p> <p>Finding 50.00 inches Code Up to 40.00 inches ADA 309, 205, 308, 606, 308.1, CA 11B-603.5</p>	<p>Relocate the dispenser to the correct height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$277</p>	<p>\$0.00</p>	
<p>Record Number 17129</p> <p>Freedom Center Mens Restroom Outer Soap</p> <p>The height of the controls and operating mechanisms for the dispenser is not at the correct height.</p> <p>Finding 45.00 inches Code Up to 40.00 inches ADA 309, 205, 308, 606, 308.1, CA 11B-603.5</p>	<p>Relocate the dispenser to the correct height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$277</p>	<p>\$0.00</p>	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17144</p> <p>Freedom Center Mens Restroom Outer</p> <p>Wall Sign</p> <p>There is no compliant signage indicating accessibility on the latch side of the entry door of the restroom.</p> <p>Finding None Found</p> <p>ADA 703, 216, 216.8, CA 11B-216.8</p>	<p>Provide compliant signage on latch side of door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 17128</p> <p>Freedom Center Mens Restroom Outer</p> <p>There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair.</p> <p>Finding 42.50 inches</p> <p>Code At least 60.00 inches</p> <p>ADA 603, 304, 304.3, 603.2, 304.3, 603.2, CA 11B-304.3</p>	<p>Modify the restroom to provide sufficient clear floor space for a turning radius in the restroom to accommodate an individual in a wheelchair.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$14,000</p>	<p>\$0.00</p>	
<p>Record Number 17115</p> <p>Freedom Center Womens Restroom</p> <p>The bottom edge of the reflective surface of the mirror is not at the correct height.</p> <p>Finding 48.50 inches</p> <p>Code Up to 40.00 inches</p> <p>ADA 603, 213, 603.3, CA 11B-603.3</p>	<p>Lower the mirror so the bottom edge of the reflective surface is no higher than recommended above the finished floor.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$300</p>	<p>\$0.00</p>	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17218 Freedom Center Womens Restroom</p> <p>The coat hook is not mounted at the correct height.</p> <p>Finding 70.75 inches Code 15.00 - 48.00 inches ADA 308, 603.4, 308.1, CA 11B-308,603.4,604.8</p>	<p>Mount the coat hook at the recommended height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$50</p>	<p>\$0.00</p>	
<p>Record Number 17211 Freedom Center Womens Restroom</p> <p>The door to the compartment does not have an accessible handle on both sides.</p> <p>Finding Not on both sides.</p> <p>ADA 404, 213, 604, 604.8, 604.8, CA 11B-404.2,604.8</p>	<p>Provide an accessible handle mounted on the door of the compartment near the latch.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$250</p>	<p>\$0.00</p>	
<p>Record Number 17213 Freedom Center Womens Restroom</p> <p>The compartment door is located in front of the water closet.</p> <p>Finding Not Located</p> <p>ADA 604.8, CA 11B-604.8</p>	<p>Reconfigure the toilet compartment to provide a compliant door that is located adjacent to the water closet.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$4,000</p>	<p>\$0.00</p>	



Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17217 Freedom Center Womens Restroom</p> <p>The inside handle is not located near the latch.</p> <p>Finding None Found</p> <p>ADA 404, 213, 604, 604.8, CA 11B-404.2,604.8</p>	<p>Adjust the inside handle so that it is located near the latch.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$129</p>	<p>\$0.00</p>	
<p>Record Number 17216 Freedom Center Womens Restroom</p> <p>The compartment door hardware is not at a compliant height.</p> <p>Finding 50.00 inches Code 34.00 - 44.00 inches</p> <p>ADA 404, 213, 604, 404.2, 604.8, CA 11B-404.2,604.8</p>	<p>Remove and relocate the door hardware.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$269</p>	<p>\$0.00</p>	
<p>Record Number 17212 Freedom Center Womens Restroom</p> <p>The clear opening width of the doorway to the compartment is less than required.</p> <p>Finding 22.00 inches Code At least 32.00 inches</p> <p>ADA 404, 404.2, 604.8, CA 11B-604.8,404.2</p>	<p>Widen the doorway to provide a compliant clear opening width when the door is open 90 degrees.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$4,000</p>	<p>\$0.00</p>	


Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17214</p> <p>Freedom Center Womens Restroom</p> <p>Door does not close automatically.</p> <p>Finding Missing Hardware</p> <p>ADA 404, 604.8, 604.8, CA 11B-604.8</p>	<p>Provide an automatic door closer, spring hinge, pull bar or accessible handle mounted on the inside of the compartment door to the compartment designated to be accessible.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$269</p>	<p>\$0.00</p>	
<p>Record Number 17215</p> <p>Freedom Center Womens Restroom</p> <p>The door to the compartment designated to be accessible in the restroom does not have appropriate accessible hardware.</p> <p>Finding Not Accessible</p> <p>ADA 404, 404.2, 309.4, 604.8, CA 11B-404.2,604.8</p>	<p>Install accessible hardware on the compartment door that does not require tight grasping, pinching, or twisting of the wrist.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$289</p>	<p>\$0.00</p>	
<p>Record Number 17209</p> <p>Freedom Center Womens Restroom</p> <p>The toilet does not provide the required distance from the center line to a fixture or wall on the wide side.</p> <p>Finding 16.00 inches</p> <p>Code At least 42.00 inches</p> <p>ADA 603, 604, CA 11B-604</p>	<p>Provide a compliant amount of clearance from the center line of the toilet to the nearest fixture or wall on the wide side.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,500</p>	<p>\$0.00</p>	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17208 Freedom Center Womens Restroom</p> <p>The flush control on the toilet is not on the wide (approach) side of the toilet.</p> <p>Finding Wrong Side of Toilet</p> <p>ADA 603, 604.6, CA 11B-604.6</p>	<p>Relocate the flush control so it is on the wide (approach) side of the toilet area. Flush controls shall be hand-operated or automatic mechanisms.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$127</p>	<p>\$0.00</p>	
<p>Record Number 17206 Freedom Center Womens Restroom</p> <p>The height of the toilet seat is not at the required height.</p> <p>Finding 16.50 inches Code 17.00 - 19.00 inches</p> <p>ADA 603, 604.4, CA 11B-604.4</p>	<p>Adjust or modify the toilet so the seat height is at the required accessible height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,707</p>	<p>\$0.00</p>	
<p>Record Number 17205 Freedom Center Womens Restroom</p> <p>The distance from the center of the toilet to the nearest side wall does not meet the required distance.</p> <p>Finding 13.75 inches on center Code 17.00 - 18.00 inches</p> <p>ADA 603, 604.2, CA 11B-604.2</p>	<p>Relocate the toilet so the distance from the center line of the toilet to the nearest side wall meets the required distance.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,500</p>	<p>\$0.00</p>	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17210 Freedom Center Womens Restroom</p> <p>There is less than the required minimum space in front of the toilet.</p> <p>Finding 29.50 inches Code At least 48.00 inches ADA 603, CA 11B-604.8</p>	<p>Create the required minimum clear space in front of the toilet.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$3,500</p>	<p>\$0.00</p>	
<p>Record Number 17116 Freedom Center Womens Restroom</p> <p>Door Sign - Female</p> <p>There is no gender use signage on the entrance door.</p> <p>Finding None Found CA 11B- 216.8,703.7</p>	<p>Post gender use signage on the center of the door at the required height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 17112 Freedom Center Womens Restroom</p> <p>Lavatory</p> <p>The pipes under the lavatory do not provide protection against contact.</p> <p>Finding Pipes not wrapped. ADA 213, 606, 606.5, CA 11B-606.5</p>	<p>Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$149</p>	<p>\$0.00</p>	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17109</p> <p>Freedom Center Womens Restroom</p> <p>Lavatory</p> <p>The apron height under the lavatory is less than the required minimum height.</p> <p>Finding 27.75 inches Code At least 29.00 inches ADA 213, 606, 306.3, CA 11B-306.3,606.2</p>	<p>Raise or replace the lavatory to provide the minimum required apron height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,500</p>	<p>\$0.00</p>	
<p>Record Number 17110</p> <p>Freedom Center Womens Restroom</p> <p>Lavatory</p> <p>The knee clearance space under the lavatory is less than the required minimum height.</p> <p>Finding 25.25 inches Code At least 27.00 inches ADA 213, 606, 606.2, 306.3, CA 11B-606.2,306.3</p>	<p>Raise or replace the lavatory to provide the minimum required knee clearance.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,286</p>	<p>\$0.00</p>	
<p>Record Number 17111</p> <p>Freedom Center Womens Restroom</p> <p>Lavatory</p> <p>The lavatory center line does not meet the minimum required distance when located adjacent to a side wall, partition or fixture.</p> <p>Finding 15.00 inches on center Code At least 18.00 inches on center CA 11B- 606.6</p>	<p>Replace or remount lavatory to meet the minimum required distance to the center line of the fixture, when located adjacent to a side wall or partition.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,500</p>	<p>\$0.00</p>	




Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17113</p> <p>Freedom Center Womens Restroom</p> <p>Lavatory</p> <p>The supply lines under the lavatory do not provide protection against contact.</p> <p>Finding Not Wrapped</p> <p>ADA 213, 606, 606.5, CA 11B-606.5</p>	<p>Insulate or otherwise configure pipes under the lavatory to protect against contact. Make certain there are no sharp or abrasive surfaces under the lavatory.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$149</p>	<p>\$0.00</p>	
<p>Record Number 17114</p> <p>Freedom Center Womens Restroom</p> <p>Lavatory</p> <p>The metered water faucet remains open for less than the required amount of time.</p> <p>Finding 6.00 seconds</p> <p>Code At least 10.00 seconds</p> <p>ADA 606.4, CA 11B-606.4</p>	<p>Provide compliant metered faucet that remains open for a compliant amount of time.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>			<p>\$0.00</p>	
<p>Record Number 17108</p> <p>Freedom Center Womens Restroom</p> <p>Paper Towel</p> <p>The height of the controls and operating mechanisms for the dispenser is not at the correct height.</p> <p>Finding 53.00 inches</p> <p>Code Up to 40.00 inches</p> <p>ADA 309, 205, 308, 606, 308.1, CA 11B-603.5</p>	<p>Relocate the dispenser to the correct height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$277</p>	<p>\$0.00</p>	




Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17107</p> <p>Freedom Center Womens Restroom</p> <p>Soap</p> <p>The height of the controls and operating mechanisms for the dispenser is not at the correct height.</p> <p>Finding 50.00 inches</p> <p>Code Up to 40.00 inches</p> <p>ADA 309, 205, 308, 606, 308.1, CA 11B-60 3.5</p>	<p>Relocate the dispenser to the correct height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$277</p>	<p>\$0.00</p>	
<p>Record Number 17117</p> <p>Freedom Center Womens Restroom</p> <p>Wall Sign</p> <p>There is no compliant signage indicating accessibility on the latch side of the entry door of the restroom.</p> <p>Finding None Found</p> <p>ADA 703, 216, 216.8, CA 11B-216.8</p>	<p>Provide compliant signage on latch side of door.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$158</p>	<p>\$0.00</p>	
<p>Record Number 17204</p> <p>Freedom Center Womens Restroom</p> <p>There are no grab bars.</p> <p>Finding None Found</p> <p>ADA 603, 609, 604.5, CA 11B-604.5</p>	<p>Install the required grab bars in the toilet compartment.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$267</p>	<p>\$0.00</p>	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17203 Freedom Center Womens Restroom</p> <p>The height of the operable parts of the seat cover dispenser is greater than the allowed maximum height.</p> <p>Finding 56.00 inches Code Up to 40.00 inches ADA 309, 205, 308, 606, 308.2, CA 11B-60 3.5</p>	<p>Relocate the seat cover dispenser to a compliant height, that provides sufficient clear floor space, and does not interfere with use of the grab bars.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$277	\$0.00	
<p>Record Number 17201 Freedom Center Womens Restroom</p> <p>There is insufficient clear floor space in the compartment.</p> <p>Finding 29.75 inches Code At least 60.00 inches ADA 603, 213, 604, 604.8, CA 11B-604.8</p>	<p>Modify or replace the compartment to provide adequate clear floor space.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$4,000	\$0.00	
<p>Record Number 17202 Freedom Center Womens Restroom</p> <p>There is insufficient clear floor space in the compartment.</p> <p>Finding 55.50 inches Code At least 59.00 inches ADA 603, 213, 604, 604.8, CA 11B-604.8</p>	<p>Modify or replace the compartment to provide adequate clear floor space.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		\$4,000	\$0.00	

Restrooms

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17199 Freedom Center Womens Restroom</p> <p>The location of the seat cover dispenser does not provide sufficient clear floor space.</p> <p>Finding Not Accessible</p> <p>ADA 304, 309.2, 305.1, CA 11B-603.5,309.2,305.1</p>	<p>Relocate the seat cover dispenser to a compliant height, that provides sufficient clear floor space, and does not interfere with use of the grab bars.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$277</p>	<p>\$0.00</p>	
<p>Record Number 17200 Freedom Center Womens Restroom</p> <p>There is no toilet paper dispenser provided on the narrow side wall.</p> <p>Finding None Found</p> <p>ADA 603, 604.7, CA 11B-604.7</p>	<p>Install a compliant toilet paper dispenser.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$277</p>	<p>\$0.00</p>	
<p>Record Number 17265 Multipurpose Room</p> <p>Drinking fountain does not provide a required fountain depth.</p> <p>Finding 12.50 inches Code At least 18.00 inches</p> <p>ADA 305, 306, 211, 602, CA 11B-602.8</p>	<p>Install a drinking fountain the meets the required minimum depth.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,500</p>	<p>\$0.00</p>	

Drinking Fountains

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17263 Multipurpose Room</p> <p>The spout outlet height is greater than required.</p> <p>Finding 40.00 inches Code Up to 36.00 inches ADA 211, 602, 602.4, CA 11B-602.4</p>	<p>Provide a spout outlet that does not exceed the required height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$627</p>	<p>\$0.00</p>	
<p>Record Number 17266 Multipurpose Room</p> <p>The drinking fountain is not set entirely in an alcove.</p> <p>Finding None Found ADA 307.2, 602.1, CA 11B-602.9</p>	<p>Provide compliant wing walls or barrier at the drinking fountain.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$640</p>	<p>\$0.00</p>	
<p>Record Number 17261 Multipurpose Room</p> <p>The provided drinking fountain is not a High/Low fountain.</p> <p>Finding Fountain Not Compliant ADA 305, 602, 211.2, CA 11B-211.2,602</p>	<p>Replace the drinking fountain with a compliant High/Low fountain.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,500</p>	<p>\$0.00</p>	


Drinking Fountains

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 17262</p> <p>Multipurpose Room</p> <p>The drinking fountain is a protruding object.</p> <p>Finding None</p> <p>ADA 305, 306, 211, 602, 307.2, CA 11B-602,307.2</p>	<p>Make sure that the fountain is not a protruding object.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$550</p>	<p>\$0.00</p>	
<p>Record Number 17264</p> <p>Multipurpose Room</p> <p>The water flow trajectory is not parallel to the front of the drinking fountain.</p> <p>ADA 602.6, CA 11B-602.6</p>	<p>Provide a water flow trajectory that is parallel to the front of the drinking fountain.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$2,875</p>	<p>\$0.00</p>	
<p>Record Number 17119</p> <p>Freedom Center Front Office Break Room</p> <p>Refrigerator - Appliance</p> <p>Appliance Reach Height in the break/conference room is not compliant.</p> <p>Finding 50.00 inches</p> <p>Code Up to 48.00 inches</p> <p>ADA 309, 205, 308, CA 11B-308,309,205</p>	<p>Make sure that the specified appliance reach height is compliant.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,200</p>	<p>\$0.00</p>	

Sinks

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16980</p> <p>Freedom Center Kitchen</p> <p>Paper Towel</p> <p>The height of the controls and operating mechanisms for the dispenser is not at the correct height.</p> <p>Finding 60.00 inches Code Up to 40.00 inches ADA 309, 205, 308, 606, CA 11B-603.5</p>	<p>Relocate the dispenser to the correct height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$180</p>	<p>\$0.00</p>	
<p>Record Number 16981</p> <p>Freedom Center Kitchen</p> <p>Soap</p> <p>The height of the controls and operating mechanisms for the dispenser is not at the correct height.</p> <p>Finding 54.00 inches Code Up to 40.00 inches ADA 309, 205, 308, 606, CA 11B-603.5</p>	<p>Relocate the dispenser to the correct height.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$180</p>	<p>\$0.00</p>	
<p>Record Number 16977</p> <p>Freedom Center Kitchen</p> <p>Sink counter height is not compliant.</p> <p>Finding 36.00 inches Code Up to 34.00 inches ADA 606.3, CA 11B-606.3</p>	<p>Provide compliant sink.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$1,800</p>	<p>\$0.00</p>	

Sinks

Finding	Recommendation	Projected Date	Actual Date	Est. Cost	Act. Cost	Photo
<p>Record Number 16978 Freedom Center Kitchen</p> <p>The pipes are not wrapped for the sink.</p> <p>Finding Not Wrapped</p> <p>ADA 606.5, CA 11B-606.5</p>	<p>Insulate or Otherwise configure pipes under the sink to protect against contact. Make certain there are no sharp or abrasive surfaces under the sink.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$149</p>	<p>\$0.00</p>	
<p>Record Number 16979 Freedom Center Kitchen</p> <p>Supply lines are not wrapped for the sink.</p> <p>Finding Not Wrapped</p> <p>ADA 606.5, CA 11B-606.5</p>	<p>Make sure that the supply lines are fully wrapped and insulated for the sink.</p>	<p>Priority Not Set</p> <p>Resolution Not Set</p> <p>Progress Not Set</p> <p>Assignment Not Set</p>		<p>\$149</p>	<p>\$0.00</p>	